


TURBO ACTION

HIGH PERFORMANCE TRANSMISSIONS

TORQUEFLITE "727" FRONT PUMP MACHINING CAUTION!!

Torqueflite Front Pump MUST be modified to run this 17509 series converter. All Turbo Action Transmissions are already modified.

Clean Up Diameter



This area must be machined to remove hump. DO NOT machine anymore then necessary to remove hump.

